

## CASE STUDY AIRPORT HOTEL

A hotel located at an airport had a tremendous problem with pigeons, sparrows and starlings.

FIG 1



A hotel located at an airport had a tremendous problem with pigeons, sparrows and starlings. Birds created huge problems on signs, ledges and inside mechanical louvers.

FIG 2



Ledges, louvers and sign letters are heavily coated with bird droppings. The wide ledge at the base of the white column is fouled with several inches of wet, heavy bird waste.

FIG 3



After a thorough cleaning with pressure washers and bactericides, the clean building is protected with Flex-Track and Translucent Bird Net.

FIG 4



Flex-Track protects the upper surfaces of the sign, while Bird Net stops the birds from entering the louvered areas above and behind the sign letters.

FIG 5



The netting is very hard to see as it excludes all birds from the louvered areas.