

## Case Studies

### CASE STUDY CHURCH

A church with an unique wooden architectural pattern was suffering from a problem with pigeon nests.

**FIG 1**



The pesky birds built nests in all of the troughs where the angled beams met the vertical supports. The glass and ground were constantly covered with droppings.

**FIG 2**



Flex-Track was installed on all the angled surfaces.

**FIG 3**



From below (looking straight up) you can see the lead wire run to each ledge.